

# HP

HP-1\*

HP-10

HP-100



\* Available on request.

Use for making torque settings on electric screwdrivers, checking torque of torque wrenches or measuring torque of various rotating units, etc.



HP-1



Model		HP-1	HP-10	HP-100
Peak measuring range	N • m		0.015 - 1.000	0.15 - 10.00
	N • mm	1.5 - 100.0		
	lbf • in	0.015 - 0.90	0.15 - 9.00	1.5 - 90.0
	(kgf • cm)		(0.15 - 10.00)	(1.5 - 100.0)
Accuracy	Within $\pm 0.5\%$ (F.S.)			
Measuring modes	TRACK, PEAK, FIRST PEAK			
External dimensions (mm)	230 × 124 × 65.2 (H)			
Weight (kg)	1.8kg			
Battery pack (charging time)	1.2V NiMH x 5 cells 1,000mA (within 6 hours)			
Continuous operating time on a full charge	8 hours			
Battery life	About 300 charges			
Exclusive battery charger	Input: AC 100-240V (50 / 60Hz) Output: DC 7.3-8V 0.5 A			